0044247

Transmittal Number: BHI-OP-00010-TR115

Date Prepared: 05/17/96

Page 1 of 1

008	Document Number: BHI-OP-00010				
H0-09	Title: 200-UP-1 PILOT-SCALE GROUNDWATER TREATMENT SYSTEM OPERATING PROCEDURES				
Instructions: (1) Remove and/or insert indicated procedure/section into manual as shown.					
(2) Sign this form and return it to Pro	cedures Coordination within	10 work	king days of	f receipt.	
Procedure/Section Numbers and Titles		Remove		Insert	
		Rev.	Date	Rev.	Date
REVISION ORDER TO BHI-OP-00010, REVISION 2, 200-UP-1 PILOT-SCALE GROUNDWATER TREATMENT SYSTEM OPERATING PROCEDURES"				A	5/17/96
NOTE: INSERT REVISION ORDER A DIRECTLY IN FRONT OF PROCEDURE BHI-OP-00010, REVISION 2.					
123456789					
TO THE PROPERTY OF THE PROPERT					
RECEIVED W					! !
B EDING #					
\ <u>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</u>	· · ·		·		
CESSING OF STATES					"
		<u> </u>			
Errors and omissions are not the responsibility of Procedures Coordination. Questions concerning format/contents of this document should be referred to Sosten DeLeon at 372-9300.					
Receipt Acknowledgment					
I have complied with the above instructions for this manual.					
DA Som	6/5/96				
Signature Date					
New address or MSIN if different than listed above:					
FOLD DOWN TO THE DOTTED LINEPLEASE DO NOT STAPLE OR TAPE.					

ERC CONTROLLED MANUAL TRANSMITTAL

EDMC

RETURN TO: Procedures Coordination, MSIN H0-10

Bechtel Hanford, Inc., 3350 George Washington Way, Richland, Washington 99352

BHI-DC-001 (01/96)

REVISION ORDER Page _1_ of _ DOCUMENT TO BE CHANGED: BHI-OP-00010 Document Type/No. Rev No. Date Rev. Order ID (Assigned by Dcc) Change Type: [X] General [] Site Spec., Site No: ____ [] Exception [] Revision Approval of this revision shall alter the document identified above for: [X] Sites [] The project as detailed in section 2 Revision Required by: _5/16/96 Initiated by: J. E. Hodgson Date Date Name Reason for change: To make the procedure more clear. DESCRIPTION OF CHANGE: Section Description Add a note that states: "Note: Insure that all ball valves identified in section 2.5.4 are closed prior to starting 2.5.1 the reconfiguration for the backwash process."

REVIEWED:

CONCUR:

Project Quality Assurance

Functional Area/Project Manager

5/15/96 Date

5/15/91

Date

BHI-PC 5/17/96